

Boeing Limited

To: G. Hardy 14-EF
M. Coffey 14-EJ

cc: D. Vezzetti 74-08

Subject: Shop Floor SHEA Compliance Advisory Number - 99-10-25-1
Shop: R-3000 Building: Flightline Column/Door: NBF & Renton

SHEA Discrepancy(ies): North Boeing Field and Renton Flightlines are not practicing safe operating practices and showing that they are taking all steps necessary to prevent spills from occurring on the Flightline as evidenced by the number of spills that have occurred at each Flightline over the past year.

1998 NBF had 6 documented spills of fuel ranging from 1 gallon to 25 gallons.

1998 Renton had 3 documented spills of fuel ranging from 1 gallon to 30 gallons.

1999 NBF has had 9 documented spills of fuel ranging from 1 gallon to 43 gallons.

1999 Renton has had 7 documented spills of fuel ranging from 1 gallon to 1000 gallons.

Corrective Action(s): Develop a process whereby spills are prevented while fueling airplanes.

Corrective Action

Completion Date: _____

Corrective Action

Verified By: _____

MBU Manager: _____
Signature

Please return to SHEA at 19-16 when corrective action has been completed.

If there are any questions, please contact the SHEA representative below.

Yvette Y. Barnett
SHEA Representative
Phone # (425)237-9263

Boeing Limited